duterference Search

	FILE 'USPATFULL, USPAT2' ENTERED AT 12:27:49 ON 17 JUL 2005
L1	988 SEA ABB=ON PLU=ON 427/389900/NCL
L2	41 SEA ABB=ON PLU=ON 427/389900/NCL
	TOTAL FOR ALL FILES
L3	1029 SEA ABB=ON PLU=ON 427/389900/NCL
L4	27302 SEA ABB=ON PLU=ON ((?OLEFIN? OR ?BUTENE? OR ?PROPENE? OR
	?ETHENE? OR ?PROPYLENE? OR ?ETHYLENE?) (5A) (?AMORPHOUS? OR
	CRYSTAL?))
L5	2305 SEA ABB=ON PLU=ON ((?OLEFIN? OR ?BUTENE? OR ?PROPENE? OR
	?ETHENE? OR ?PROPYLENE? OR ?ETHYLENE?) (5A) (?AMORPHOUS? OR
	CRYSTAL?))
	TOTAL FOR ALL FILES
L6	29607 SEA ABB=ON PLU=ON ((?OLEFIN? OR ?BUTENE? OR ?PROPENE? OR
	?ETHENE? OR ?PROPYLENE? OR ?ETHYLENE?) (5A) (?AMORPHOUS? OR
	CRYSTAL?))
L7	30 SEA ABB=ON PLU=ON L4 AND L1
L8	1 SEA ABB=ON PLU=ON L5 AND L2
T 0	TOTAL FOR ALL FILES
L9	31 SEA ABB=ON PLU=ON L6 AND L3
L10 L11	
TIT	1 SEA ABB=ON PLU=ON L8 AND ?VISCOSITY? TOTAL FOR ALL FILES
L12	
L13	
L14	1 SEA ABB=ON PLU=ON L11 AND CARPET?
DIA	TOTAL FOR ALL FILES
L15	9 SEA ABB=ON PLU=ON L12 AND CARPET?
L16	· · · · · · · · · · · · · · · · · · ·
L17	8 SEA ABB=ON PLU=ON L10 AND CARPET?
L18	1 SEA ABB=ON PLU=ON L11 AND CARPET?
	TOTAL FOR ALL FILES
L19	9 SEA ABB=ON PLU=ON L15
L20	1 SEA ABB=ON PLU=ON L17 AND ?FUSION?
L21	0 SEA ABB=ON PLU=ON L18 AND ?FUSION?
	TOTAL FOR ALL FILES
L22	1 SEA ABB=ON PLU=ON L19 AND ?FUSION?
	D BIB AB
	D KWIC
L23	
L24	0 SEA ABB=ON PLU=ON L18 AND ?ENTHALPY?
	TOTAL FOR ALL FILES
L25	0 SEA ABB=ON PLU=ON L19 AND ?ENTHALPY?
L26	7 SEA ABB=ON PLU=ON L13 NOT L20
L27	1 SEA ABB=ON PLU=ON L14 NOT L21
т э о	TOTAL FOR ALL FILES
L28 L29	8 SEA ABB=ON PLU=ON L15 NOT L22
ב שנו	8 FOCUS L28 1-
	D 1-8 BIB AB

Search

```
FILE 'USPATFULL, USPAT2' ENTERED AT 12:27:49 ON 17 JUL 2005
L1
            988 SEA ABB=ON PLU=ON 427/389900/NCL
             41 SEA ABB=ON PLU=ON 427/389900/NCL
L2
     TOTAL FOR ALL FILES
L3
           1029 SEA ABB=ON PLU=ON 427/389900/NCL
T.4
          27302 SEA ABB=ON PLU=ON ((?OLEFIN? OR ?BUTENE? OR ?PROPENE? OR
                ?ETHENE? OR ?PROPYLENE? OR ?ETHYLENE?) (5A) (?AMORPHOUS? OR
                CRYSTAL?))
           2305 SEA ABB=ON PLU=ON ((?OLEFIN? OR ?BUTENE? OR ?PROPENE? OR
L5
                ?ETHENE? OR ?PROPYLENE? OR ?ETHYLENE?) (5A) (?AMORPHOUS? OR
                CRYSTAL?))
     TOTAL FOR ALL FILES
          29607 SEA ABB=ON PLU=ON ((?OLEFIN? OR ?BUTENE? OR ?PROPENE? OR
L6
                ?ETHENE? OR ?PROPYLENE? OR ?ETHYLENE?) (5A) (?AMORPHOUS? OR
                CRYSTAL?))
1.7
             30 SEA ABB=ON PLU=ON L4 AND L1
L8
              1 SEA ABB=ON PLU=ON L5 AND L2
     TOTAL FOR ALL FILES
L9
             31 SEA ABB=ON PLU=ON L6 AND L3
L10
             19 SEA ABB=ON PLU=ON L7 AND ?VISCOSITY?
L11
              1 SEA ABB=ON PLU=ON L8 AND ?VISCOSITY?
     TOTAL FOR ALL FILES
L12
             20 SEA ABB=ON PLU=ON L9 AND ?VISCOSITY?
              8 SEA ABB=ON PLU=ON L10 AND CARPET?
L13
              1 SEA ABB=ON PLU=ON L11 AND CARPET?
L14
     TOTAL FOR ALL FILES
L15
              9 SEA ABB=ON PLU=ON L12 AND CARPET?
L16
              9 FOCUS L15 1-
L17
              8 SEA ABB=ON PLU=ON L10 AND CARPET?
L18
              1 SEA ABB=ON PLU=ON L11 AND CARPET?
     TOTAL FOR ALL FILES
L19
              9 SEA ABB=ON PLU=ON L15
L20
              1 SEA ABB=ON PLU=ON L17 AND ?FUSION?
L21
              0 SEA ABB=ON PLU=ON L18 AND ?FUSION?
     TOTAL FOR ALL FILES
L22
              1 SEA ABB=ON PLU=ON L19 AND ?FUSION?
               D BIB AB
               D KWIC
L23
              O SEA ABB=ON PLU=ON L17 AND ?ENTHALPY?
              0 SEA ABB=ON PLU=ON L18 AND ?ENTHALPY?
L24
     TOTAL FOR ALL FILES
             O SEA ABB=ON PLU=ON L19 AND ?ENTHALPY?
L25
              7 SEA ABB=ON PLU=ON L13 NOT L20
L26
L27
              1 SEA ABB=ON PLU=ON L14 NOT L21
     TOTAL FOR ALL FILES
L28
             8 SEA ABB=ON PLU=ON L15 NOT L22
L29
              8 FOCUS L28 1-
               D 1-8 BIB AB
     FILE 'CAPLUS, WPIX, JAPIO, COMPENDEX, JICST-EPLUS' ENTERED AT 12:43:13 ON
     17 JUL 2005
          52960 SEA ABB=ON PLU=ON ((?OLEFIN? OR ?BUTENE? OR ?PROPENE? OR
L30
                ?ETHENE? OR ?PROPYLENE? OR ?ETHYLENE?) (5A) (?AMORPHOUS? OR
                CRYSTAL?))
          13901 SEA ABB=ON PLU=ON ((?OLEFIN? OR ?BUTENE? OR ?PROPENE? OR
L31
                ?ETHENE? OR ?PROPYLENE? OR ?ETHYLENE?) (5A) (?AMORPHOUS? OR
                CRYSTAL?))
L32
           5586 SEA ABB=ON PLU=ON ((?OLEFIN? OR ?BUTENE? OR ?PROPENE? OR
                ?ETHENE? OR ?PROPYLENE? OR ?ETHYLENE?) (5A) (?AMORPHOUS? OR
               CRYSTAL?))
L33
          6507 SEA ABB=ON PLU=ON ((?OLEFIN? OR ?BUTENE? OR ?PROPENE? OR
                ?ETHENE? OR ?PROPYLENE? OR ?ETHYLENE?) (5A) (?AMORPHOUS? OR
```

```
CRYSTAL?))
L34
            364 SEA ABB=ON PLU=ON ((?OLEFIN? OR ?BUTENE? OR ?PROPENE? OR
                  ?ETHENE? OR ?PROPYLENE? OR ?ETHYLENE?) (5A) (?AMORPHOUS? OR
                  CRYSTAL?))
      TOTAL FOR ALL FILES
       79318 SEA ABB=ON PLU=ON L6
L35
L36
              11 SEA ABB=ON PLU=ON L30 AND (CARPET? (10A) TUFT?)
              17 SEA ABB=ON PLU=ON L31 AND (CARPET? (10A) TUFT?)
L37
               4 SEA ABB=ON PLU=ON L32 AND (CARPET? (10A) TUFT?)
0 SEA ABB=ON PLU=ON L33 AND (CARPET? (10A) TUFT?)
0 SEA ABB=ON PLU=ON L34 AND (CARPET? (10A) TUFT?)
L38
L39
L40
      TOTAL FOR ALL FILES
L41
             32 SEA ABB=ON PLU=ON L35 AND (CARPET? (10A) TUFT?)
L42
             426 SEA ABB=ON PLU=ON L30 AND (MELT (5A) VISCOSITY?)
·L43
             256 SEA ABB=ON PLU=ON L31 AND (MELT (5A) VISCOSITY?)
L44
             100 SEA ABB=ON PLU=ON L32 AND (MELT (5A) VISCOSITY?)
L45 .
              33 SEA ABB=ON PLU=ON L33 AND (MELT (5A) VISCOSITY?)
              0 SEA ABB=ON PLU=ON L34 AND (MELT (5A) VISCOSITY?)
      TOTAL FOR ALL FILES
            815 SEA ABB=ON PLU=ON L35 AND (MELT (5A) VISCOSITY?)
L47
L48
              25 SEA ABB=ON PLU=ON L42 AND (ENTHALPY?)
               9 SEA ABB=ON PLU=ON L43 AND (ENTHALPY?)
L49
               0 SEA ABB=ON PLU=ON L44 AND (ENTHALPY?)
L50
               1 SEA ABB=ON PLU=ON L45 AND (ENTHALPY?)
L51
               0 SEA ABB=ON PLU=ON L46 AND (ENTHALPY?)
L52
     TOTAL FOR ALL FILES
             35 SEA ABB=ON PLU=ON L47 AND (ENTHALPY?)
L53
             19 SEA ABB=ON PLU=ON L47 AND (ENTHALPY?)

19 SEA ABB=ON PLU=ON L42 AND (ENTHALPY? (5A) FUSION?)

3 SEA ABB=ON PLU=ON L43 AND (ENTHALPY? (5A) FUSION?)

0 SEA ABB=ON PLU=ON L44 AND (ENTHALPY? (5A) FUSION?)

0 SEA ABB=ON PLU=ON L45 AND (ENTHALPY? (5A) FUSION?)

0 SEA ABB=ON PLU=ON L46 AND (ENTHALPY? (5A) FUSION?)
L54
L55
L56
L57
L58
      TOTAL FOR ALL FILES
L59
            22 SEA ABB=ON PLU=ON L47 AND (ENTHALPY? (5A) FUSION?)
L60
              0 SEA ABB=ON PLU=ON L54 AND CARPET?
L61
               0 SEA ABB=ON PLU=ON L55 AND CARPET?
L62 -
              0 SEA ABB=ON PLU=ON L56 AND CARPET?
L63
              O SEA ABB=ON PLU=ON L57 AND CARPET?
            0 SEA ABB=ON PLU=ON L58 AND CARPET?
L64
     TOTAL FOR ALL FILES
L65
              0 SEA ABB=ON PLU=ON L59 AND CARPET?
L66
              30 SEA ABB=ON PLU=ON L36 OR L54
L67
              20 SEA ABB=ON PLU=ON L37 OR L55
L68
               4 SEA ABB=ON PLU=ON L38 OR L56
L69
               0 SEA ABB=ON PLU=ON L39 OR L57
L70
               0 SEA ABB=ON PLU=ON L40 OR L58
     TOTAL FOR ALL FILES
L71
              54 SEA ABB=ON PLU=ON L41 OR L59
L72
              48 DUP REM L71 (6 DUPLICATES REMOVED)
                 D 1-48 BIB AB
     FILE 'EPFULL, FRFULL, GBFULL, PATDPAFULL, PCTFULL, RDISCLOSURE,
     USPATFULL, USPAT2' ENTERED AT 13:06:58 ON 17 JUL 2005
            8764 SEA ABB=ON PLU=ON ((?OLEFIN? OR ?BUTENE? OR ?PROPENE? OR
                  ?ETHENE? OR ?PROPYLENE? OR ?ETHYLENE?) (5A) (?AMORPHOUS? OR
                  CRYSTAL?))
L74
              35 SEA ABB=ON PLU=ON ((?OLEFIN? OR ?BUTENE? OR ?PROPENE? OR
                  ?ETHENE? OR ?PROPYLENE? OR ?ETHYLENE?) (5A) (?AMORPHOUS? OR
                  CRYSTAL?))
L75
            1331 SEA ABB=ON PLU=ON ((?OLEFIN? OR ?BUTENE? OR ?PROPENE? OR
                  ?ETHENE? OR ?PROPYLENE? OR ?ETHYLENE?) (5A) (?AMORPHOUS? OR
                 CRYSTAL?))
L76
              44 SEA ABB=ON PLU=ON ((?OLEFIN? OR ?BUTENE? OR ?PROPENE? OR
```

```
?ETHENE? OR ?PROPYLENE? OR ?ETHYLENE?) (5A) (?AMORPHOUS? OR
                  CRYSTAL?))
L77
            6548 SEA ABB=ON PLU=ON ((?OLEFIN? OR ?BUTENE? OR ?PROPENE? OR
                  ?ETHENE? OR ?PROPYLENE? OR ?ETHYLENE?) (5A) (?AMORPHOUS? OR
                  CRYSTAL?))
L78
             113 SEA ABB=ON PLU=ON ((?OLEFIN? OR ?BUTENE? OR ?PROPENE? OR
                  ?ETHENE? OR ?PROPYLENE? OR ?ETHYLENE?) (5A) (?AMORPHOUS? OR
                  CRYSTAL?))
           27302 SEA ABB=ON PLU=ON ((?OLEFIN? OR ?BUTENE? OR ?PROPENE? OR
L79
                  ?ETHENE? OR ?PROPYLENE? OR ?ETHYLENE?) (5A) (?AMORPHOUS? OR
                  CRYSTAL?))
L80
            2305 SEA ABB=ON PLU=ON ((?OLEFIN? OR ?BUTENE? OR ?PROPENE? OR
                  ?ETHENE? OR ?PROPYLENE? OR ?ETHYLENE?) (5A) (?AMORPHOUS? OR
                  CRYSTAL?))
     TOTAL FOR ALL FILES
          46442 SEA ABB=ON PLU=ON L6
L81
L82
              21 SEA ABB=ON PLU=ON L73 AND (CARPET? (10A) TUFT?)
L83
                0 SEA ABB=ON PLU=ON L74 AND (CARPET? (10A) TUFT?)
L84
               4 SEA ABB=ON PLU=ON L75 AND (CARPET? (10A) TUFT?)
L85 .
               O SEA ABB=ON PLU=ON L76 AND (CARPET? (10A) TUFT?)
L86
              34 SEA ABB=ON PLU=ON L77 AND (CARPET? (10A) TUFT?)
L87
               1 SEA ABB=ON PLU=ON L78 AND (CARPET? (10A) TUFT?)
             123 SEA ABB=ON PLU=ON L79 AND (CARPET? (10A) TUFT?)
L88
              11 SEA ABB=ON PLU=ON L80 AND (CARPET? (10A) TUFT?)
L89
     TOTAL FOR ALL FILES
L90
             194 SEA ABB=ON PLU=ON L81 AND (CARPET? (10A) TUFT?)
              11 SEA ABB=ON PLU=ON L81 AND (CARPET? (10A) TOFT?)
11 SEA ABB=ON PLU=ON L82 AND (MELT? (5A) VISCOSITY?)
0 SEA ABB=ON PLU=ON L83 AND (MELT? (5A) VISCOSITY?)
1 SEA ABB=ON PLU=ON L84 AND (MELT? (5A) VISCOSITY?)
0 SEA ABB=ON PLU=ON L85 AND (MELT? (5A) VISCOSITY?)
11 SEA ABB=ON PLU=ON L86 AND (MELT? (5A) VISCOSITY?)
0 SEA ABB=ON PLU=ON L87 AND (MELT? (5A) VISCOSITY?)
L91
L92
L93
L94
L95
L96
L97
              37 SEA ABB=ON PLU=ON L88 AND (MELT? (5A) VISCOSITY?)
               2 SEA ABB=ON PLU=ON L89 AND (MELT? (5A) VISCOSITY?)
L98
     TOTAL FOR ALL FILES
L99
              62 SEA ABB=ON PLU=ON L90 AND (MELT? (5A) VISCOSITY?)
L100
               0 SEA ABB=ON PLU=ON L91 AND (?ENTHALPY? (5A) FUSION?)
L101
               0 SEA ABB=ON PLU=ON L92 AND (?ENTHALPY? (5A) FUSION?)
L102
               0 SEA ABB=ON PLU=ON L93 AND (?ENTHALPY? (5A) FUSION?)
L103
               0 SEA ABB=ON PLU=ON L94 AND (?ENTHALPY? (5A) FUSION?)
               0 SEA ABB=ON PLU=ON L95 AND (?ENTHALPY?
L104
                                                               (5A) FUSION?)
               0 SEA ABB=ON PLU=ON L96 AND (?ENTHALPY?
L105
                                                               (5A) FUSION?)
               1 SEA ABB=ON PLU=ON L97 AND (?ENTHALPY? (5A) FUSION?)
L106
               0 SEA ABB=ON PLU=ON L98 AND (?ENTHALPY? (5A) FUSION?)
T-107
     TOTAL FOR ALL FILES
L108
               1 SEA ABB=ON PLU=ON L99 AND (?ENTHALPY? (5A) FUSION?)
                 D BIB AB
```